
What caused the cracks

WATER PRESSURE



Steel plate —

High-density – extruded polystyrene

LTA's findings:

• Water had accumulated at the roadside due to the heavy rain and seeped under the road base. The built-up water pressure caused the temporary section of the road to heave, resulting in the cracks on the road surface.

