


To be demolished

Crossheads on uncompleted stretch of ill-fated viaduct to be torn down because they are unsafe

Proposed viaduct

Crossheads in this section of the two-lane viaduct are to be demolished



Tampines Junior College

East Spring Secondary School

Tampines Leisure Park

FLORA DRIVE

The Japanese Primary School

East Spring Primary School

UPPER CHANGI ROAD NORTH

TAMPINES STREET 33

Incident location

PAN-ISLAND EXPRESSWAY



UPPER CHANGI FLYOVER

